



Worldwide repairs carried out with PolymerMetall®

REP-# 043



In a transformer station plant oil leakages at welding seams of a conservator were repaired with the Direct-MM-Bonding method by using MM-metal oL-steelceramic, Hardener red and Hardener yellow.

MultiMetall
the MetalExistenceCompany®