



Worldwide repairs carried out with PolymerMetal®

REP-# 041



Sealing of a large transformer in a power station. The leakage was sealed with MM-metal oL-steelceramic and Hardener red using the Direct-MM-Bonding method. Then a layer of MM-metal oL-steelceramic and Hardener yellow was applied to the first layer.

MultiMetall
the MetalExistenceCompany®