



*Worldwide repairs carried out with PolymerMetal®*

**REP-# 088**



A machine casing was repaired by using MM-metal oL-steelceramic and Hardener red and afterwards Hardener yellow. The application has been done using the Direct-MM-Bonding technology.

**MultiMetall**  
the MetalExistenceCompany®